

High Valley Estates Apartments

BEFORE



Property

AFTER



Property



Manager's Office



Manager's Office



Patios and Balconies back of Building 4



Patios and Balconies back of Building 4

High Valley Estates Apartments

BEFORE

AFTER



Courtyard



Courtyard



Back of Building 7



Back of Building 7



Front of Building 7



Front of Building 7 New Drainage Installed and Chain Fence Removed

High Valley Estates Apartments

BEFORE



Western Complex Courtyard Non Accessible

AFTER



Western Complex Courtyard New Accessible Route



Side of Building 2 Stairs Not Code Compliant



Side of Building 2 Stairs Code Compliant



Back of Building 6



Back of Building 6

High Valley Estates Apartments

BEFORE

AFTER



Back of Building 1



Back of Building 1



ADA Kitchen



ADA Kitchen



Typical Kitchen



Typical Kitchen

High Valley Estates Apartments

BEFORE



ADA Shower Stall

AFTER



ADA Shower and Tub



ADA Bathroom



ADA Bathroom



Typical Living/Dining Room



Typical Living Room/Dining Room

High Valley Estates Apartments

BEFORE



Handrail at Unit Stairs

AFTER



New safety wall at Unit Stairs



Laundry Room



Laundry Room with New Accessible Bathroom



Playground



New Playground

High Valley Estates Apartments

BEFORE



Trash Bins

AFTER



New Trash Enclosure